Priority Level: Medium — Recommended Action for Affected Systems		
	All Service Personnel	Bulletin: SB-013 Date: 7/26/2005
	EA SPORTS™ PGA TOUR® Golf Challenge Edition Upgrade Cabinets Only	
Issue:	Dollar Bill Validator (DBV) does not register input when the cabinet is upgraded to Challenge Edition .	

Symptom: DBV does not register money that is inserted, but you hear the coin mech click. Coin inputs

register properly. The system computer has a version 1.4 Nytric USBI/O card.

Solution: Press the Operator button and check the **Nytric Version** displayed in the **Machine Menu**

screen. This is the version of the Nytric USBI/O card installed. If the system has a 1.4 version


card, perform the steps below to change the DBV coin signal from COIN1 to COIN0.

If the system does not have a 1.4 version Nytric card, contact Tech Support.

- 1. Locate the white wire that connects to the coin mechs. Trace the wire; it will pass through a shrink tube. Locate the white wire where it comes out of the shrink tube. Loosen the wire from cable ties as necessary to give you some slack to work with.
- 2. Locate the two yellow wires from the DBV connector. Trace the wires to where they are butt-spliced to a white, and a black-white wire, respectively.
- 3. Cut the yellow wire that is spliced to the white wire, just below the butt splice. (This wire connects to Pin 7 of the 9-pin DBV connector.)
- 4. Splice the cut yellow wire into the white wire from the coin mechs, below the shrink tube (this is the wire that you traced in step 1).

Important: Use electrical tape as needed to make sure the splice is well insulated. If the wires short against metal they will cause coin inputs to register.

The figure below shows a suggested method of splicing the wires using a quick-connect splicer.



5. Test the DBV and coin mechs following this procedure to verify proper operation.