



Priority Level: High — Immediate Action Required		
Attention:	All Service Personnel	Bulletin: SB-012 Date: 5/4/2005
Products:	EA SPORTS™ MADDEN NFL™ FOOTBALL Field Test Systems for: EA GAMES™ <i>Need for Speed™</i> Underground EA SPORTS™ PGA TOUR® Golf Challenge Edition	
Issue:	Some Money Controls Dollar Bill Validators are not properly grounded, causing intermittent malfunctioning.	

Symptom: Money Controls brand Dollar Bill Validators (DBVs) are not properly grounded on some systems. This can cause the DBVs to malfunction intermittently.

Solution: If your Money Controls DBV has a green ground wire, check to see where the wire is connected. (Some Money Controls DBVs do not have a ground wire.)

If the green ground wire is connected to a DBV mounting screw, move the ground wire to the coin vault grounding lug, as shown in the figure below. You will need a 10-32 Kep nut to secure the wire to the coin vault ground lug.

