



Priority Level: Medium — Recommended Action		
Attention:	All Service Personnel	Bulletin: SB-042 Date: 2/21/2008
Products:	EA SPORTS™ NASCAR Racing, Standard Cabinets Only	
Issue:	Cabinet sections may separate after rough handling.	

Symptom: A small number of EA SPORTS™ NASCAR Racing Standard Cabinets have had incidents of cabinet sections separating, particularly after rough handling during shipping.

Deluxe and Motion Cabinets are not affected.

Solution: As a proactive approach, GLOBAL VR recommends reinforcing the cabinets by installing screws as shown in the two drawings in this bulletin.

If you have any questions or concerns, please contact GLOBAL VR support.

Important: Pre-drill each hole with a 1/16-inch drill bit to prevent splitting the wood cleats.




Figure 1 of 2




Figure 2 of 2