



PLEASE READ IMMEDIATELY

PRODUCT:	Last Bounty Hunter	Total # of Pages 1
DATE:	11-20-03	

Last Bounty Hunter Triggers

To: Service and Parts.

Triggers are shipping out to Distribution for all LBH games that have already shipped. Any new LBH game will have the modified trigger.

Problem: The triggers on the guns are breaking causing the gun not to fire.

Solution: Install the new modified trigger.

Scope: All Last Bounty Hunter games from Serial number LBH00001 - LBH00144 and LBH00309 - LBH00409

Directions: Remove the right side of the red gun housing by removing the five T10 security Torx screws. Remove the old trigger from the spring and from under the PCB capture plate. Reattach the trigger to the spring and reinstall the trigger into pivot holes. Reinstall the right side red gun housing.



Global VR Customer Service
408 501-0000 X 2458 (Mark Sherman)