

---

**PRODUCT:** Breeders' Cup – Tournament Edition

**BULLETIN:** SB-005

**ISSUE:** Free Credits with Service Button

**DATE:** 04-25-05

## Breeders' Cup – Free Credits with Service Button

We received a report from an Operator who had a player give himself free credits by using a slim piece of metal to slide under the Control Panel hood and press the service button.

Stand at the front of the cabinet, looking at the Control Panel hood. There is small gap that runs the width of the cabinet where the bottom control panel hood meets the wood of the cabinet. It is in this small gap that a player can use a thin piece of metal or wood to slide through the gap and press the Service Button. UltraCade Technologies recommends two different solutions for this problem.

1. Disconnect the wires from the Service button so that a player can not use the button.
2. Bend the metal plate that the Service button is mounted to back into the cabinet so that the buttons can not be pressed from an object that is pushed through the gap under the control panel hood. When finished the metal plate should be mounted horizontally instead of vertically in the cabinet.

This will be corrected in the next revision of the cabinet design. We are getting ready to start production of this new design (Rev 5) below are the features. If you have suggestions, please get them to us immediately.

- \* Control Panel now wood, hood extends over control panel, panel hinges forward
- \* Locks moved from side to front of hood, conventional locks used allowing operator replacement
- \* Back Door lock installed
- \* Shelf across top prevent DBA access from back door
- \* Second set of whip/hold buttons installed for 2 player Head2Head QuickRace on single cabinet
- \* Casters moved to outside, levelers to inside
- \* New Coin Mech installed in front face of control panel
- \* Coin Box built to prevent access to coin box from back door
- \* Light bar on top showing 1st, 2nd and 3rd
- \* CC reader moved to front face of control panel